


# PT21MD

## HSS deuvelfrees HSS plug cutter

Frezen voor het maken van deuvels in zacht en middelhard hout.  
Cutters designed to make plugs in soft and medium-hardness wood.



D mm	H mm	A mm	Z	Max. opm Max RPM	Code Code	SAP SAP
8	140	13x50	4		<b>PT21MD0080</b>	F03FA03801
10	140	13x50	4		<b>PT21MD0100</b>	F03FA03802
12	140	13x50	4		<b>PT21MD0120</b>	F03FA03803
14	140	13x50	4		<b>PT21MD0140</b>	F03FA03804
15	140	13x50	4		<b>PT21MD0150</b>	F03FA03805
16	140	13x50	4		<b>PT21MD0160</b>	F03FA03806
18	140	13x50	4		<b>PT21MD0180</b>	F03FA03807
20	140	13x50	5		<b>PT21MD0200</b>	F03FA03808
25	140	13x50	5		<b>PT21MD0250</b>	F03FA03809
30	140	13x50	5		<b>PT21MD0300</b>	F03FA03810
35	160	16x50	5		<b>PT21MD0350</b>	F03FA03811
40	160	16x50	6		<b>PT21MD0400</b>	F03FA03812

